

Joules	Minimum Engagement
0.5	5
1	5
1.25	5
1.5	5
1.75	20
2	50
2.25	50
2.5	80
2.75	80
3	100
3.25	100
3.5	NA
3.75	NA
4.5	NA

ROF	Add On
25	20
35	50
45+	80